

MONUMENT RECORD

Corner I.D. #


mk-11

STATE OF INDIANA - COUNTY OF MONROE

Section Fifteen (15), Township 7 North, Range 1 East

Monument Description & Remarks: Found U.S.F.S. Monument @ West 1/4 corner
(County sign &)
of section. Monument was solid in ground. U.S.F.S. sign & post S 04° W,
1.70' from Monument. (See attached for detailed drawing of monument).

Recovery Tie Drawing



State of Indiana
County of Monroe

I, Michael W. Friley, County Surveyor M.W.F., hereby certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; and the above data is given under my hand and seal this 16th day of February, 1996 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Monroe County Surveyor's Office
United States Government Agency

Monroe County Surveyor
Title

Field Book:

96-01

Page:


23

MONUMENT RECORD


Section	<u>15</u>
Township	<u>7 North</u>
Range	<u>1 East</u>

Corner I.D. _____

Description: U.S.F.S. Monument - 3" Aluminum Cap Set in 3"
Iron Pipe. (Please refer to attached "Recovery
Tie Drawing")



Not To Scale



CORNER I.D.

M - 11

MONUMENT RECORD



STATE OF INDIANA - COUNTY OF MONROE

SECTION 15 AND 16, TOWNSHIP 7 NORTH, RANGE 1 EAST

MONUMENT DESCRIPTION & REMARKS

2½" I.D. x 36" LONG GALVANIZED IRON PIPE FILLED WITH CONCRETE
AND CAPPED WITH A 3" BRASS TABLET SET BY THE FOREST SERVICE.

RECOVERY TIE DRAWING



(●) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS
DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE
WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF
THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND
THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL
THIS 3 DAY OF JUNE, 1981 A.D.

SPACE
RESERVED
FOR
RECORDING
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. _____

OR _____

UNITED STATES GOVERNMENT AGENCY

TOWNSHIP:

POLK

CORNER I.D.

M - 11

TITLE

RECORDED
A.M. _____ P.M. 1:38 ✓

Polk. M11

MAR 18 1985

168700

Virginia H. Hudson
RECORDER MONROE CO., IND.
R9-7150-15 (5/64)

155 PAGE 512

CERTIFIED LAND CORNER RESTORATION

State of Indiana }
County of Monroe } ss.

I, Edmund O. Farkas, do hereby certify that on the 3rd day of June, 1981,
I found evidence of the reestablished the $\frac{1}{4}$ section corner of Sections 15 and 16
Township 7 North, Range 1 East, Second Principal Meridian, as described
hereon; and that ~~from this evidence~~ I established a new monument and accessories as described hereon to per-
petuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Original monument was a wood post
set in 1814. Original bearing trees:

B.Oak	B.Oak
12"	12"
N66E	S66W
12 Links	21 Links

Subsequent survey by M.H. Buskirk,
Monroe Co. Surveyor, filed in Monroe Co.
Surveyor's Office, 1881, Book 2, Page 340.
His bearing trees were:


Quaking Aspen	Red Oak
8"	3"
S66 $\frac{1}{2}$ W	S35E
8 Links	9 Links

Description of corner evidence found:


No evidence of the corner was found.
There are old fences running north,
south and east from general area of
the corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

Based on a survey of the Section line between Sections 15 and 16, the Forest Service set
a 2 $\frac{1}{2}$ " I.D. X 36" long galvanized iron pipe filled with concrete and capped with a 3"
brass tablet stamped, as shown below, as the Quarter corner to Sections 15 and 16 at the
single proportional distance from the section corners, north and south and with considera-
tions given to the S1/16 for alignment purposes. Established the following witnesses:



Sugar Maple	Hickory
5"	3"
N63E	S16E
9.0 Feet	6.3 Feet



● = Corner monument restored
□ =

Resident witnesses Kenneth W. Anderson

Dated at Bedford Indiana, this 11th day of June
1981.

Signature Edmund O. Farkas Title County Surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. S0114

Office of _____ County of _____
I hereby certify that the within instrument was filed in this office for record
on the _____ day of _____ 19_____, and was filed in Book
No. _____ Page No. _____ of County Records.

Signature _____ Title _____

Township 7 North Range 1 East, Section 16 & 15, Index No. L-3, Page No. _____
this instrument was prepared

Index No. L13
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7100-74 (Rev. 5/80)
826-531

T. 7N R. 1E Mer. N.F. _____ County Monroe State IN.
44 Corner common to sections 16 15 and _____

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed _____		Year of search _____ By _____	
Original monument: _____ (Wood post, stone, pile of stones, pipe, etc.)		Monument found _____	
Bearing Trees		Original Bearing Trees Found	
Species _____	_____	Species _____	_____
Diameter _____	_____	Diameter _____	_____
Bearing _____	_____	Bearing _____	_____
Distance _____	_____	Distance _____	_____
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration Found	
Year surveyed _____ By _____		Year of search _____ By _____	
Where filed or recorded _____		_____	
Monument _____ (Original, concrete post, iron rod, etc.)		_____	
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. 20' E of N-S fence and about 100' NE of house. A pasture is to the W of the corner and a shortleaf pine plantation is 60'-70' to the SE.
A 3" diameter aluminum pipe, concrete filled, was set 6" above ground and surrounded by a mound of rocks

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

B.T.
Maple
8"

B.T.
Hick.
5"

N 63° E
8.96'

S 14° E
6.3'

At time of search:

1. Did you have the record description?
Yes _____ No _____

2. How was search area located?
Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. L-13
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 806-924

T. 7N R. 15E 2nd Mer. N.F. Hoosier County Monroe State Ind.
1/4 Section Corner common to sections 15, 16, and

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1814</u>		Year of search _____	By _____
Original monument <u>Wood Post</u> (Wood post, stone, pile of stones, pipe, etc.)		Monument found _____	
Bearing Trees Species <u>B.O.</u> <u>B.O.</u> Diameter <u>12"</u> <u>12"</u> Bearing <u>N 66° E</u> <u>S 66° W</u> Distance <u>12 LKS.</u> <u>21 LKS.</u>		Original Bearing Trees Found Species _____ Diameter _____ Bearing _____ Distance _____	
Subsequent Corner Restoration Year surveyed <u>1881</u> By <u>BUSKIRK</u> Where filed or recorded <u>MON. CO. ENG. OFFICE</u> Monument _____ (Original, concrete post, iron rod, etc.)		Evidence of Subsequent Corner Restoration Found Year of search <u>1981</u> By <u>Tim Cummings</u> <u>found stake in ground & in road</u> <u>riden down 11/20/81</u> <u>Survey, no one here at that time</u> <u>1981 - Tim Cummings</u>	
Bearing Trees, Reference Objects Species <u>QUAKING ASH</u> <u>R. OAK</u> Diameter <u>8"</u> <u>3"</u> Bearing <u>S 66.5° W</u> <u>S 35° E</u> Distance <u>8 LKS.</u> <u>9 LKS.</u>		Bearing Trees, Reference Objects _____ _____ _____ _____	



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____


Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. 1981 - 15' E of fence line
approx 100' NE of house - approx 60' NW of Shortleaf pine
plantation - east of pasture

Perpetuation Record

Monument and accessories established. Include brief description of area.
3" dia alum pipe concrete filled 6" out of ground
surrounded by mound of rocks - 3" brass cap

Sugar maple stick
8" 4"
N 63° E S 16° E
9.0' 6.3'



At time of search:

1. Did you have the record description?
Yes _____ No _____

2. How was search area located?
Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____